REPORT OF CHANNEL CONDITIONS							Page 1 of 1		
(FOR CHANNELS 400 FEET WIDE OR GREATER) (ER 1130-2-316)]	Mav 2002	
TO: Executive Director, Port Authority Commonwealth of Puerto Rico, San Juan, Puerto Rico				FROM USACE. District Engineer Attn: CESAJ-CO-OM Jacksonville. Florida					
RIVER/HARBOR NAME AND STATE Mayaguez Harbor, Puerto Rico				MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD					
NAME OF CHANNEL	Date	AUTHOR	IZED PROJ	ECT Left		Left	Right	Right	
	of Survey	Width	Length	Depth	Outside Quarter	Inside Quarter	Inside Quarter	Outside Quarter	
		(feet)	(miles)	(feet)	(feet)	(feet)	(feet)	(feet)	
Entrance Channel: from entrance, 2,000 feet seaward of Red Buoy-6, to basin entrance.	Mar-2002	1000-500	0.4	30	24.9 (1)	30.8	30.5	29.3 (1)	
Inner Basin: From Red Buoy-6 to Terminus of Inner Basin.	Mar-2002	500	0.2	30	23.8 (2)	23.2 (2)	23.2 (2)	16.4 (2)	

Remarks:

- (1) Shoaling along the northern edge of channel from 850 feet seaward of and extending to red Buoy-6. Spot shoaling also along southern edge of channel from 800 feet seaward of red Buoy-6 and extending 400 feet eastward.
- (2) Shoaling along south and east perimeter of basin, extending north of Buoy-10. Least depth occurring in southeast corner of basin.